



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 23018 Rev A

**TO:** Garmin GNS™ 430(W)/530(W) Series Owners and Operators  
**DATE:** March 14, 2023  
**SUBJECT:** GNS 430(W)/530(W) Series Repair Service Changes

---

### **PRODUCTS AFFECTED**

All WAAS and Non-WAAS GNC® 420, GNS 430, GNS 530, GPS 400, and GPS 500 products are affected.

### **ISSUE**

Due to multiple component availability limitations, comprehensive repair service for the Garmin GNS 430(W)/530(W) series is expected to become limited in the years ahead. Initially, these limitations are estimated to impact a small percentage of repairs beginning in 2024.

First introduced in 1998, Garmin has offered repair service for the GNS 430/530 series for 25 years. Garmin plans to continue offering repair service when the components required for a specific repair remain available. Database updates and technical support will also remain available.

We encourage GNS 430(W)/530(W) series owners to begin considering their transition strategy to newer generation products. Please visit [www.Garmin.com/AviationGPS](http://www.Garmin.com/AviationGPS) to review upgrade options.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a  
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).